

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: AURORA, CITY OF

Community No: 185172

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

### 1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

### 2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	00-05-0810A	04/21/2000	114 5TH STREET	1851720001B	18029C0192C
LOMA	05-05-2810A	05/05/2005	JOHN WALKER'S SUBDIV, LOT 42 -- 311 HANOVER AVENUE	1851720001B	18029C0191C
LOMA	07-05-4252A	07/03/2007	HENRY WALKER'S 2ND ADDITION, IN-LOTS 59 & 64 -- 114 GREEN BOULEVARD & 417 BROADWAY STREET (IN)	1851720001B	18029C0192C
LOMA	08-05-3048A	05/13/2008	LANE'S SUBDIV, LOT 9 -- 264 DECATUR STREET	1851720001B	18029C0192C
LOMA	08-05-2549A	06/10/2008	799 WESTSIDE DRIVE -- PORTION OF SECTION 32, T5N, R1W	1851720001B	18029C0192C

### 3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

## PRELIMINARY SUMMARY OF MAP ACTIONS

Community: AURORA, CITY OF

Community No: 185172

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

1. Insufficient information available to make a determination.
2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
4. Revised hydrologic and hydraulic analyses.
5. Revised topographic information.

**4. LOMCs To Be Redetermined**

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		